Approved For Release 2003/12/23: CIA-RDR33-02415A000300150054-2 COPY 3 OF 3

25X1A

25X1A

25X1A 25X1A

25X1A

25X1A

3 January 1962

SUBJECT: Monthly Commander's Report
TO: Chief, DPD
A. General
1. Our flying training and maintenance programs for the month ended up very close to what we had actually scheduled. The only cancellations were the 24 hour delay in a training mission damage) and a delay in the post-inspection test flight due to inclement weather. In an effort to insure maximum proficiency prior to standdown, most of our sorties were of short duration.
2. We survived the holiday season without serious incidents of any nature on 20 December gave a Christmas dinner party for and members of my immediate staff. This event was held at the airport and no outsiders were present at this dinner.
3. On 23 December our unit hosted the children of our project at a small party in the Hostel. This appeared to be highly successful and I believe created a lot of good will.
4. The new BX and Commissary cards have been received. Now all military personnel have adequate buying power on a par with other military personnel in the area and all griping toward this area should be eliminated. Our morale continues to be good and the Hostel area is continually becoming more livable. A piano has been purchased and installed in the area which adds to the atmosphere since we have the talent available within the unit.
B. Administration

Approved For Release 2003/12/23 : CIA-RDP33-02415A000300150054-

1-2	Idea-	062	7
-	COPY	3 c. 3	TT ke 2 v

}	
25X1A	2
25X1	3. Total expenditures for December 1961 were Breakdown enclosed in attachment 1.
	C. <u>Operations</u>
25X1A 25X1A 25X1A	1. During the month of December 1961, 11 training and one ferry missions were flown in the for a total of 30:50 hours. The ferry mission was performed on 16 December as a result of the diversion of on 15 December due to strong crosswinds at 60:35 T-33 hours were flown with training accomplished for December and also for the six month period ending 31 December shown in Attachment 2. Hours flown and training accomplished for the calendar year 1961 are shown in Attachment 3.
25X1A	2. One training mission was cancelled 14 December due to a ground incident. The MA-2 air hose broke loose at the first coupling and whipped against the left side of the fuselage, damaging the left engine scoop in three places (photos forwarded as attachment 4). Repair was accomplished and the mission was flown on 15 December. The following corrective action has been taken to prevent recurrence:
	a. MA-2 air hoses re-checked for deterioration.
!	 b. Hose couplings checked for proper installation of Mormon clamps. c. Torque radius re-checked on Mormon clamps.
	 d. Hose connections re-wrapped with plastic tape instead of gun tape, to allow visual inspection. e. Momentary contact switch installed on MA-2's.
0EV1	3. Two pilot meetings were conducted during the month, covering flight safety, TOC's, Unit SOP's, SB's being complied with in this inspection, and normal and emergency procedures. A Top Secret document inventory was completed on 29 December. Mission profiles 33, 33-1, 34, and 35 were designed including special fuel curves, and were added to the library of training missions. A new fuel curve was formulated for 695 gallon fuel load. The plotting of Chicom commercial stations continues and mainland area WAC charts have been ordered to facilitate location of these stations. Ten mission overlays were completed by the Photo Interpreter. The Photo Interpreter also conducted instruction classes for the
25X1	for the in plotting and marking overlays.



3

									a 2 m	
	4. A Unit Simuliarity with an SOP #25 (Steril: comprehensive. The	nd accuracy	of Unit Mesion	SOP's	ift). T	n the	except tres we	re adequ	ate and	e ges
	5	bo e	flown	76.10	hours	10	aı	nd 118:00) hours in	WBI
1.										
	TOTAL 76:10	_	WX 1:05	GCI O	GCA 13	ADF 18	SFO 5	NIGHT 0:55	HOOD 0:50	
	T-33 TOTAL 118:0		WX 10:00	GCI O	GCA 46	ADF	SFO 8	NIGHT 26:45	HOOD 20:35	
W V	6. With the or the month were f price scheduled on iew of the forece SCM is scheduled	exception of 2 hour or to 29 and 30 D	duration enterination ecomber was not ry, and	n to 1 ng ins , but re-so with	nsure pection were continued with the continued wit	n. Ma ancell d unti	intena ed due 1 2 Ja on of	nce test to weat nuary 19 one prof	flights her. In 62. A sec	cond
	ach, all		COURTG9:	1 60. 00	21 0110					
h	No major Mate capability is now with later models aigh effectiveness receipt of supplications averaging even leastic of that activities	well stabil s. Overall s. Pipeline ss from this ss intransit	ized the logistic time for divising time.	rough cs suf rom ou on ave (This	the report bur submarages excel	y sion	of a	ntinued requisit	at its usition to the	ual e ts
. 1	S. Maintenance									
1	l. The one this inspection p devision, and S/B required the bulk tanks, required s make the installa and outboard to m on new fuel stra Fuel Pump and mai bracket was rewor	eriod nine in 557, Revis: of the total one rework in tion. Hydrake connect iner bracker	ion of the same of	the Simours structuel Punt the re-loc sump t	ipper ! expendeure and mp Brace new fucated to anks. membe	Fined. Fank Fined. Solution Composite with the composite of the composi	uel Troberts by 536 conents as rep ainer. conne ap tan ick up	anefer Co, replace in the cositioned Mountine tion with shut of existing	onfiguration of some to i forward on clamps the Hydraul of valve	ic

Approved For Release 2003/12/23 CIA-RDP33-02415A000300150054-2

ation holes. Orginial fuel lines required clearance due to new lines being installed, clearance was obtained by re-locating clamps and spacers. LH sump

25X1A 25X1A

25X1A

25X1A 25X1A

25X1A

25X1A

25X1A

Handard have DE immedian and Shaine twin nun completed December 28.

tank scupper drain cup had to be removed to be trimmed and reworked to fit LH sump tank. RH sump tank was received with all the pilot shut off valves and floats installed, IH sump tank valves and floats were installed at this station. During fuel flow check out RH Aux Tank and Slipper would not feed to sump tank, due to a faulty check valve. S/B 588, Sump Tank Brain & S/B 589. Manifold Lines Drain were not completed during this inspection, S/B's were received after sump tanks were installed in article.

J. Personal Equipment and Medical		Q= 8	

- 3. During the standdown period the P.E. Van was completely modernized and repainted.
- 4. The T-33 survival equipment was examined and the kits were improved with additional and replacement items.
- 5. The doctor downtown whose signature we use has requested that he personally document all immunization records. Though this gives him greater legal protection it creates another security leak and requires two to three days to complete action on the records. We are trying to work out a more satisfactory compromise.
- 6. Medical supply requests are now being cabled direct to Headquarters in anticipation that this method will expedite the receipt of equipment here; a trial order is in process now.

25X1A

25X1A

25X1A

5

	H.	Special	Equipment
--	----	---------	-----------

1. Our main concern this month has been overhaul and inspection of shutters and their components. This type of inspection is more 25X1A intensive than the normal pre and post flight inspections. Components reaching limits in time or cycles are overhauled or replaced as per our SOP's. 2. We completed the first of a series of four service bulletins. The

rest will be completed as received. Since most service bulletins represent improvement to the equipment, they are complied with immediately on receipt.

is normal. There are no particular 3. Liaison with problems in this area.

4. All leaves have been completed and Special Equipment is again at full strength.

I. Installations

1. Hostel Area

a. Preventative maintenance on the window air conditioner units, started in November, was completed during this reporting period.

b. A 7.5 KW heating unit was installed in the 5 ton air conditioner in the mess hall - bar area. Desired temperature is controlled by a wall thermostat.

2. Hangar Area

a. The installation of the electric demand meter and transformer was completed during the month.

b. A complete overhaul of the existing phone system has been initiated. The field line originally used is being replaced with multi-pair cables and terminal boxes to facilitate maintenance and future requirem

ana	Incm.e	Ledam.encure.	
		 	25X1A
			23/1/

5	Incl	osur	es.	1
	-	D	- 1-	4

Breakdown of December expenses, 1 copy h/w
 Breakdown of flying time, 1 copy h/w

3. Annual Flying Accomplishment Chart, 1 copy h/w

4. 5 Photos of Damage, u/s/c.

5. Identities, in trip, u/s/c.

Distributions:

0 & 2 - Hqs, w/atts as stated

MACORIA Approved For Release 2003/12/23: CIA-RDP33-02415A000300150054-2

25X1A

25X1A

25X1A